

Attachment 1 - Property Photos - 57 Fleury Street




**Grind and tuckpoint
defective joints on
chimney**

**New
Portland
cap**

Grind and tuckpoint defective joints in this area

Cut drip edges

Grind/remove loose debris and parge



Cut drip edges

Grind and tuckpoint
defective joints in this area




Grind/remove loose
debris and parge




**Grind and tuckpoint
defective joints in this
area**

Cut drip edges



Cut drip edge

Grind and tuckpoint defective joints in this area




Cut drip edge

**Grind and tuckpoint
defective joints in this
area**

**Grind/remove loose debris
and parge**

**New cap
and
crown**



**Grind and tuckpoint defective
joints in this area**







**Grind and tuckpoint
defective joints in this
area**