

2024



# Aurora Cenotaph



The following is a short report to outline recommendations and options for the Cenotaph located at

**Aurora War Memorial Peace Park  
Younge St Aurora Ontario**

A complete on-site inspection was performed on Dec 10 , 2:00 p.m the following is an update to the original submitted report. New slides are highlighted in Orange block



2024



# Aurora Cenotaph



## LEAD LETTERING


It is understood that

Each letter height is 1 ½ inch high & 1 inch wide

The spelling of FRED LUXTON too FRED LUXON ( remove the T)

Remove the M.C after the Name Wilfred P. Petermann

We will also perform a complete inspection of all lettering and touch up or repaint letters as required





2024



ON SITE INSPECTION :  
December 10 24 UPDATE

# Aurora Cenotaph




## LEAD LETTERING

**AFTER CLOSE INSPECTION  
Of the Lead lettering**

**Will confirm that all lead  
lettering will be painted , re  
hand painting , Currently the  
lettering is inconsistent , some  
darker than others**

**As well There is a small amount  
of Engraving that requires  
freshen up , not all engraving is  
painted, and we will not paint  
what was originally painted**





2024



ON SITE INSPECTION :  
December 10 24 UPDATE

# Aurora Cenotaph





## LEAD LETTERING

**AFTER CLOSE INSPECTION  
Of the Lead lettering**

**Will confirm that all lead lettering will be painted , re hand painting , Currently the lettering is inconsistent , some darker than others**

**As well There is a small amount of Engraving that requires freshen up , not all engraving is painted, and we will not paint what was originally painted**





2024



# Aurora Cenotaph



## CLEANING

Structures of this nature are subjected to soiling of various types

We propose an entire site & structure application / cleaning of a BIOCIDE cleaner, power washing on granite elements and surrounding cement pads & natural stone elements.



Tom Klaasen 519 383 2998

[memorialrestorations@gmail.com](mailto:memorialrestorations@gmail.com)

[www.memorialrestorations.com](http://www.memorialrestorations.com)



2024



ON SITE INSPECTION:  
December 10 24 UPDATE

# Aurora Cenotaph



## MASONRY JOINTING



I performed a visual inspection of the joints while on site, there is a considerable amount of jointing ( low level , within my sightline ) it's difficult to determine the state of joints higher than my viewpoint, but we will inspect while cleaning, and report back significant issues immediately .

Tom Klaasen 519 383 2998

[memorialrestorations@gmail.com](mailto:memorialrestorations@gmail.com)

[www.memorialrestorations.com](http://www.memorialrestorations.com)



2024



ON SITE INSPECTION :  
December 10 24 UPDATE

# Aurora Cenotaph



MASONRY JOINTING



Tom Klaasen 519 383 2998

[memorialrestorations@gmail.com](mailto:memorialrestorations@gmail.com)

[www.memorialrestorations.com](http://www.memorialrestorations.com)



2024



ON SITE INSPECTION :  
December 10 24 UPDATE

# Aurora Cenotaph



MASONRY JOINTING



Tom Klaasen 519 383 2998

[memorialrestorations@gmail.com](mailto:memorialrestorations@gmail.com)

[www.memorialrestorations.com](http://www.memorialrestorations.com)