
#### Attachment 3



## Presentation Overview

Purpose of today's meeting:

 Methodology for the evaluation of cultural heritage resources as part of the Review of the Aurora Register Project (i.e. evaluation of listed properties)



## Presentation Overview

- 1. Aurora Register Project Background;
- 2. Review Legislated requirements for heritage evaluations (PPS, OHA);
- 3. Review methodology for the Review of the Aurora Register project;
- 4. Review examples in Aurora;
- 5. Next Steps.



# Aurora Register Project – RFP

### **Project RFP Goals**

- Comprehensive review of the Aurora Register to ensure it maintains an accurate and informative inventory of the Town's heritage resources:
  - Determine level of importance of each property;
  - Prioritize conservation efforts;
  - Identify those properties which could be designated under the OHA;
  - Remove irrelevant properties which have no value to the community.

DE FACTORY









## Aurora Register Project - Phased Work Plan

Phase 1

- First SC Meeting January, 2021
- Evaluation Criteria
- Research & Data Collection (inventory completed July)

Phase 2

- Evaluate listed properties
- Prepare final list of recommendations

\* We are here

Phase 3

• Consult with MHAC & Council on recommendations

Phase 4

- Revise Reports, Final recommendations to MHAC & Council
- Update Register of Heritage Resources



# Aurora Register Project

#### What is the need?

- Updated PPS (2020) and OHA (2021)
- 431 Listed Properties
- Outdated Information
  - Some of which dating back to 1970s/1980s
- Difficulties when processing applications
  - Staff cannot quickly ascertain if a property is of CHVI or not
- Some properties have changed over time or been removed and are no longer of CHVI

DE FACTORY

AUROR



# Classification Systems (OHTK)

- The current Aurora Evaluation system uses a numerical classification system
  - Adding up points = Group 1, Group 2, Group 3
  - Example: "is it early"

Pre 1851 – 1881 : (Excellent = 30)
 1882 – 1914 : (Good = 20)
 1915 – 1945 : (Fair = 10)
 1947 – present : (Poor = 0)

Pre 1851 : (Bonus – 10)

- Municipalities moving away from evaluation systems based on numerical scoring. Understand how O-Reg 9/06 is intended to be interpreted and applied:
  - Is it early based on the context? (i.e. Aurora vs. N-O-T-L)
  - Is it Pre-Confederation (1867)
  - Understanding that it doesn't need to be early to be worthy of long-term conservation



DE FACTORY

AUROR

### **Presentation Overview**

Methodology for the Aurora Register Project:

- Those properties which are not good candidates for conservation are removed;
- Those which are of major heritage value or at risk are prioritized for designation; and
  - Practicality of the designation process
- Those other properties would remain on the register and could be designated later (i.e. "work plan").



#### Methodology Framework

#### PPS 2020

Significant: means

in regard to cultural heritage and archaeology, resources that have been determined to have cultural heritage value or interest. Processes and criteria for determining cultural heritage value or interest are established by the Province under the authority of the Ontario Heritage Act. (i.e. O-Reg 9/06)

#### Ontario Heritage Took Kit, Heritage Evaluation

Individual properties being considered for protection under section 29 must undergo a more rigorous evaluation than is required for listing. The evaluation criteria set out in Regulation 9/06 essentially form a test against which properties must be assessed. The better the characteristics of the property when the criteria are applied to it, the greater the property's cultural heritage value or interest, and the stronger the argument for its long-term protection.

DE FACTORY







DE FACTORY

AUROR



# Condition & Integrity (OHTK)

- Condition: Decay of elements
- Integrity: Original features retained (or not)
- Poor condition and/or integrity has an impact on whether or not long-term conservation should be pursued







2101101111

Example: Good condition, poor integrity



# Classification System for the Review of the Aurora Register Project

ch Landy

John De

ermain de la	Zero to Minimal Value	=	Should be considered for Removal from the Register	Machell Wm Grad
ichael 30	Moderate Value	=		Sco. Grat
Walter Scott	Major Value and/or At <mark>Risk</mark>	=	Part IV Designation	Hod hand



#### Removed

2002 Vandorf Sideroad



75 George Street



**Remain Listed** 

59 Tyler Street



1978 Vandorf Sideroad



**Designated (short-listed)** 

50 Wellington St. East



57 Mosley Street





#### **Recommended for Removal from the Register**

2002 Vandorf Sideroad





75 George Street








### 2002 Vandorf Sideroad





2002 Vandorf Sideroad






• 2002 Vandorf Sideroad





• 2002 Vandorf Sideroad



#### 2002 Vandorf Sideroad (None/Minimal – Remove from the Register) Value: O-Reg 9/06 Sub-Criteria: (Minimal, Moderate, Description: Major) None Has value because it is considered: ■ Minimal ☐ Rare, Altered (unknown style) ■ Moderate ■ Unique Constructed bet. 1954 - 1963 ■ Major Design/ ■ Representative Physical ☐ Early (Pre-Confederation) **Wood Frame** Has value because it demonstrates a: ■ Poor Condition 1.5 storeys ☐ High degree of craftsmanship/artistic merit Loss of Integrity ☐ High degree of technical/scientific achievement ☐ At Risk No information which provides evidence of a significant event, *Direct* associations with a significant: ■ None theme, person, family, activity, etc. Theme ■ Minimal associated with the existing Event Historical/ Person lot/welling. ■ Moderate Associative May have been constructed by Activity ■ Major Organization/Institution members of the Baber family in 1956 (original Baber home at 1978 Vandorf Sideroad) Is *important* in its ability to: Does not define, maintain, or ☐ Define the character of the area support character of the area. ■ None ☐ Maintain the character of an area No important physical, **■**Minimal ☐ Support the character of an area Demonstrates that it is *important* in its: functional, visual, links. ■ Moderate Contextual Physical, functional, visual or historical link to its ■ Major Located adjacent to the original surroundings Baber family home ■ Landmark status Not a landmark.

75 George Street









### 75 George Street (None/Minimal – Remove from the Register)

O-Reg 9/06	Sub-Criteria:	Description:	Value: (Minimal, Moderate, Major)
Design/ Physical	Has value because it is considered:  □ Rare, □ Unique □ Representative □ Early (Pre-Confederation) Has value because it demonstrates a: □ High degree of craftsmanship/artistic merit □ High degree of technical/scientific achievement	<ul> <li>Former WWII-era bungalow removed ("victory house")</li> <li>21<sup>st</sup> Century (new construction)</li> </ul>	<ul> <li>None</li> <li>Minimal</li> <li>Moderate</li> <li>Major</li> <li>Poor Condition</li> <li>Loss of Integrity</li> <li>At Risk</li> </ul>
Historical/ Associative	Direct associations with a significant:  ☐ Theme ☐ Event ☐ Person ☐ Activity ☐ Organization/Institution	<ul> <li>21<sup>st</sup> Century (new construction)</li> <li>Lot fabric has no significant historical/associative value</li> </ul>	■ None ■ Minimal ■ Moderate ■ Major
Contextual  MHBC	Is important in its ability to:  ☐ Define the character of the area ☐ Maintain the character of an area ☐ Support the character of an area ☐ Demonstrates that it is important in its: ☐ Physical, functional, visual or historical link to its surroundings ☐ Landmark status	<ul> <li>No important physical, functional, visual, or historic links to its surroundings.</li> <li>Not a landmark.</li> </ul>	<ul><li>None</li><li>Minimal</li><li>Moderate</li><li>Major</li></ul>

#### Remain Listed (consider designation in the future)

#### 59 Tyler Street





1978 Vandorf Sideroad







## 59 Tyler Street







### 59 Tyler Street


1878 County Atlas

- Not included in FIPs
- LACAC research
  - Summaries of tax rools, census, title searches
- Regency characteristics
- 1870s
- Property directly associated with Walter Henry Machell
- Existing house likely not the birth-place of Walter Machell (previously thought to be constructed in the 1850s)









#### 59 Tyler Street (Moderate value – Remain on the Register) Value: O-Reg 9/06 Sub-Criteria: (Minimal, Moderate, Description: Major) ■ None Has value because it is considered: 1870s ■ Minimal ☐ Rare, Regency characteristics ■ Moderate □ Unique Hip roof – single storey ■ Major Design/ Representative Physical ☐ Early (Pre-Confederation) Likely constructed of bricks Has value because it demonstrates a: ■ Poor Condition from the Machell brickyard ☐ High degree of craftsmanship/artistic merit ☐ Loss of Integrity ☐ High degree of technical/scientific achievement ☐ At Risk Direct associations with a significant: Property associated with the ■ None Theme Machell family; ■ Minimal ■ \_Event Historical/ Existing building likely the Person ■ Moderate **Associative** Activity Major residence of Walter Henry Organization/Institution Machell Is *important* in its ability to: ☐ Define the character of the area ■ None ☐ Maintain the character of an area Historically linked to local ■ Minimal Support the character of an area industry (brickyard) ■ Moderate Demonstrates that it is *important* in its: Contextual Physical, functional, visual or historical link to its ■ Major Not a landmark. surroundings ■ Landmark status

## 1978 Vandorf Sideroad (The Baber House)





1978 Vandorf Sideroad (The Baber House)					
O-Reg 9/06	Sub-Criteria:	Description:	Value: (Minimal, Moderate, Major)		
Design/ Physical	Has value because it is considered:  □ Rare, □ Unique □ Representative □ Early (Pre-Confederation)  Has value because it demonstrates a: □ High degree of craftsmanship/artistic merit □ High degree of technical/scientific achievement	<ul> <li>Brick Classical Revival</li> <li>1880s</li> <li>Common in Ontario</li> <li>Integrity retained</li> <li>Original verandah removed</li> </ul>	<ul> <li>□ None</li> <li>□ Minimal</li> <li>■ Moderate</li> <li>□ Major</li> <li>□ Poor Condition</li> <li>□ Loss of Integrity</li> <li>□ At Risk</li> </ul>		
Historical/ Associative	Direct associations with a significant:  ☐ Theme ☐ Event ☐ Person ☐ Activity ☐ Organization/Institution	<ul> <li>Built for Fred Ransom (farmer, made maple syrup)</li> <li>Baber family home</li> </ul>	□ None □ Minimal □ Moderate □ Major		
Contextual  MHBC	Is important in its ability to:  ☐ Define the character of the area ☐ Maintain the character of an area ☐ Support the character of an area ☐ Demonstrates that it is important in its: ☐ Physical, functional, visual or historical link to its surroundings ☐ Landmark status	<ul> <li>Context has changed, no longer a farm complex.</li> <li>Became 1 acre lot by 1939</li> <li>Not important physical, functional, visual, links.</li> <li>Baber family later constructed a house next door in 1956</li> <li>Not a landmark.</li> </ul>	□ None □ Minimal □ Moderate □ Major		

#### **Designated (short-listed)**

50 Wellington St. East





57 Mosley Street







### 50 Wellington Street East






### 50 Wellington Street East

- "Andrews-Morrison House"
- C. 1855
- Gothic Revival cottage
- Plan 107, Pt lot 19
- Assoc. with Edward Andrews (tailor) and George Morrison (carriage maker)










1878 County Atlas



#### 50 Wellington Street East (Consider Part IV Designation) Value: O-Reg 9/06 Sub-Criteria: Description: (Minimal, Moderate, Major) ■ None Has value because it is considered: Gothic Revival Cottage; ■ Minimal ☐ Rare, ■ Moderate **□ ⊌**nique c. 1855 Design/ Representative ■ Major Physical ■ Early (Pre-Confederation) Has value because it demonstrates a: ■ Poor Condition ☐ High degree of craftsmanship/artistic merit □ Loss of Integrity ☐ High degree of technical/scientific achievement At Risk Direct associations with a significant: ■ None **Andrews-Morrison House** Theme ■ Minimal Event Edward Andrews (tailor) Historical/ Person ■ Moderate Associative George Morrison (carriage Activity ■ Major maker) Organization/Institution Is important in its ability to: ☐ Define the character of the area ■ None ☐ Maintain the character of an area ■ Minimal Support the character of an area Part of the Wellington St. E. Moderate Demonstrates that it is *important* in its: Contextual streetscape ☐ Physical, functional, visual or historical link to its ■ Major surroundings ■ Landmark status

## 57 Mosley Street





### 57 Mosley Street (Methodist Episcopal Church/Rising Sun Masonic Lodge)

O-Reg 9/06	Sub-Criteria:	Description:	Value: (Minimal, Moderate, Major)
Design/ Physical	Has value because it is considered:  □ Pare, □ Unique □ Representative □ Early (Pre-Confederation)  Has value because it demonstrates a: □ High degree of craftsmanship/artistic merit □ High degree of technical/scientific achievement	<ul> <li>Gothic Revival Church (1877)</li> <li>Unique elements as a result of use as a Masons Lodge (since 1885)</li> <li>Built by Cane &amp; Sons</li> <li>Alterations which have taken on value as part of its use as a Masonic Lodge</li> <li>Some unsympathetic alterations</li> </ul>	<ul> <li>□ None</li> <li>□ Minimal</li> <li>□ Moderate</li> <li>□ Major</li> <li>□ Poor Condition</li> <li>□ Loss of Integrity</li> <li>□ At Risk</li> </ul>
Historical/ Associative	Direct associations with a significant:  ☐ Theme ☐ Event ☐ Person ☐ Activity ☐ Organization/Institution	<ul> <li>Associated with two institutions which have had a significant impact on the local community</li> </ul>	□ None □ Minimal □ Moderate □ Major
<b>MHBC</b> xtual	Is important in its ability to:  Define the character of the area Alaintain the character of an area Support the character of an area Demonstrates that it is important in its: Physical, functional, visual or historical link to its	<ul> <li>Supports the Southeat Old Aurora neighbourhood;</li> <li>Local landmark</li> </ul>	<ul><li>□ None</li><li>□ Minimal</li><li>□ Moderate</li><li>□ Major</li></ul>

### **Concluding Statements**

- PPS 2020 directs municipalities to use O-Reg 9/06
- Determine whether or not a property meets the criteria:
  - To what extent does a property meet that criteria?
  - Is it direct and/or important?
  - Retained its integrity?
  - Is it at risk?
  - Does it warrant long-term conservation of its physical attributes?
  - If the physical attributes are removed could the historical/associative value be commemorated?



### **Next Steps**

- Support from this Steering Committee for the methodology and the use of O-Reg 9/06
- MHBC to continue to evaluate properties
  - Bring forward to Steering Committee at next meetings
- Present to Council (fall 2021)
- Council formal adoption and recognition of Ontario Regulation 9/06
  - Staff/MHAC to Use *O-Reg 9/06* in other applications (i.e. adding properties to the register

CATHERIY

 Next Presentation to MHAC: Final Recommendations (Spring 2022)




### **Next Steps**


• Further training on the use of O-Reg 9/06

 Changes to the OHA in July 2021 require updates to the existing OHTK

 Opportunities for heritage staff and Committees in Ontario to participate in future training sessions provided by the Ministry







#### Ontario Heritage Act

#### **ONTARIO REGULATION 9/06**

#### CRITERIA FOR DETERMINING CULTURAL HERITAGE VALUE OR INTEREST

- 1. The property has design value or physical value because it,
  - i. is a rare, unique, representative or early example of a style, type, expression, material or construction method,
  - ii. displays a high degree of craftsmanship or artistic merit, or
  - iii. demonstrates a high degree of technical or scientific achievement.
- 2. The property has historical value or associative value because it,
  - has direct associations with a theme, event, belief, person, activity, organization or institution that is significant to a community,
  - ii. yields, or has the potential to yield, information that contributes to an understanding of a community or culture, or
  - iii. demonstrates or reflects the work or ideas of an architect, artist, builder, designer or theorist who is significant to a community.
- 3. The property has contextual value because it.
  - i. is important in defining, maintaining or supporting the character of an area,
  - ii. is physically, functionally, visually or historically linked to its surroundings, or
  - iii. is a landmark. O. Reg. 9/06, s. 1 (2).



# **Public Input & Consultation**

 Properties considered for removal from the Register would be put forward to the next agenda of the Steering Committee.

 All recommendations to be considered by MHAC and Council.



